























US and Metric Thread Sizes

US Thread Sizes



Metric Thread Pitches



| 0 | 1 | 2 | 3 | 4 | 5 | 6 inches
Scale Check: After printing, measure ruler above to ensure correct scale